

MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN

PAGE 1 of 9

1/9

CONF. NO.: UNASSIGNED




Fig. 1A



MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. B RE-LINING TUBING DUGGAN

PAGE 2 of 9




Fig. 2A

MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN PAGE 3 of 9




Fig. 1B




Fig. 2B

MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN PAGE 4 of 9




Fig. 3

MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN

PAGE 5 of 9

CONF. NO.: UNASSIGNED






Fig. 4



MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN PAGE 6 of 9




Fig. 5



TRADEMA

MRKS/0110 10/601,405 June 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN PAGE 7 of 9

CONF. NO.: UNASSIGNED




Fig. 6A




Fig. 6B





Fig. 7



INVENTOR:

MRKS/0110 10/601,405 JUNE 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN

PAGE 8 of 9

8/9

CONF. NO.: UNASSIGNED




Fig. 9



MRKS/0110 10/601,405 June 23, 2003 WEATHERFORD/LAMB, INC. BORE-LINING TUBING DUGGAN

PAGE 9 of 9

CONF. NO.: UNASSIGNED




Fig. 10




Fig. 11